# Part 573 Safety Recall Report

Manufacturer Name :Nissan North America, Inc.Submission Date :JUN 24, 2022NHTSA Recall No. :22V-457Manufacturer Recall No. :R22A2 R22A3

### Manufacturer Information :

Manufacturer Name : Nissan North America, Inc. Address : P. O. BOX 685001 Franklin TN 37068-5009 Company phone : 800-647-7261

## Vehicle Information :

Vehicle 1:	2020-2021 Nissa	n Frontier			
Vehicle Type :	LIGHT VEHICLES				
	PICKUP TRUCK				
Power Train :					
Descriptive Information :	This issue is specific to Nissan Titan and Frontier vehicles equipped with 9-speed transmissions. No other Nissan or INFINITI vehicles are affected.				
Production Dates :	JUN 10, 2020 - JU	N 25, 2021			
VIN Range 1:	Begin :	NR	End :	NR	□ Not sequential
Vehicle 2:	2022-2022 Nissa	n Frontier			
Vehicle Type :	LIGHT VEHICLES				
Body Style :	PICKUP TRUCK				
Power Train :	GAS				
Descriptive Information :	This issue is specific to Nissan Titan and Frontier vehicles equipped with 9-speed transmissions. No other Nissan or INFINITI vehicles are affected.				
Production Dates :	JUL 13, 2021 - JU	N 14, 2022			
VIN Range 1:	Begin :	NR	End :	NR	Not sequential
Vehicle 3:	2020-2022 Nissa	n Titan			
Vehicle Type :	LIGHT VEHICLES				
Body Style :	PICKUP TRUCK				
Power Train :					
Descriptive Information :	This issue is specific to Nissan Titan and Frontier vehicles equipped with 9-speed transmissions. No other Nissan or INFINITI vehicles are affected.				
<b>Production Dates :</b>	DEC 13, 2019 - JL	JN 10, 2022			
VIN Range 1:	Begin :	NR	End:	NR	Not sequential
viiv italige 1.	0		2.1.4		Not sequential

The information contained in this report was submitted pursuant to 49 CFR \$573



NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Number of potentially involved : 180,176 Estimated percentage with defect : 1%

云 🔨 🗛 🖈

**Population :** 

22V-457

#### **Description of Defect :**

Description of the Defect :	Due to dimensional variation during the manufacturing process, reduced clearance may cause contact between the edge of the parking pawl and the boss on the transmission case, which may result in non-engagement of the parking pawl.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	If this occurs, an affected vehicle may move after placing the shifter into 'Park.' If the customer does not engage the parking brake, potential for movement of the vehicle increases the risk of injury or crash.
Description of the Cause :	NR
Identification of Any Warning that can Occur :	There is no preceding warning.

#### **Involved Components :**

Component Name 1:	CASE-AUTO TRANS	
Component Description :	Automatic Transmission	
Component Part Number :	31311 X280A	

#### **Supplier Identification :**

#### **Component Manufacturer**

Name : JATCO

Address : 1974 Midway Lane Smyrna Tennessee 37167 Country : United States

#### **Chronology**:

See attached electronic Part 573 for chronology

The information contained in this report was submitted pursuant to 49 CFR \$573

## Part 573 Safety Recall Report

22V-457

Page 3

#### **Description of Remedy :**

Description of Remedy Program : A remedy plan for all affected vehicles is currently under development.

When the final remedy plan is available, Nissan will mail final remedy notification letters and include a statement concerning reimbursement for the cost of obtaining a pre-notification remedy for a subject vehicle that was no longer under warranty at the time of a repair.

How Remedy Component Differs NR from Recalled Component : Identify How/When Recall Condition NR was Corrected in Production :

#### **Recall Schedule :**

Description of Recall Schedule :	Dealers will be notified on July 8, 2022. Nissan will mail interim notification letters to all affected owners beginning July 20, 2022,
	advising them to apply the parking brake whenever they park their vehicle.
Planned Dealer Notification Date :	JUL 08, 2022 - NR
Planned Owner Notification Date :	JUL 20, 2022 - NR

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573