#### The information contained in this report was submitted pursuant to 49 CFR §573

# Part 573 Safety Recall Report

Manufacturer Name :Autosales Inc.Submission Date :DEC 23, 2020NHTSA Recall No. :20E-093Manufacturer Recall No. :NR

#### **Manufacturer Information :**

Manufacturer Name : Autosales Inc.

Address : 1200 Southeast Ave Tallmadge OH 44278 Company phone : 2303030

#### **Equipment Information :**

Brand / Trade 1:	Summit Racing
Model :	3-Ton Jack Stand
Part No. :	SUM-918005
Size :	3 Ton
Function :	Vehicle Support
Descriptive Information :	After conducting quality testing, inspections, and an analysis of customer feedback relative to the 3-Ton Jack Stand (the "Product") manufactured by Haining Lee Ding Machinery Co. Ltd., it was determined by Summit Racing that a recall of the Product was appropriate due to quality concerns. On July 3, 2019, Summit Racing received 300 units of the Product from the Manufacturer. Upon analysis of customer feedback, Summit Racing found that prior to July 3, 2019, the customer return rate for this Product was 0.8% of all sales of the Product, with only one known customer return due to warranty or quality reasons. After July 3, 2019, Summit Racing found that the customer returns due to 3.2% of all sales of the Product, with a total of eight customer returns due to warranty or quality reasons. Summit Racing's records reflect that after July 3, 2019, it sold a total of 433 units of the Product, 14 units of the Product that may be defective and held by customers. Summit Racing has further determined that of the 419 units, a total of 251 units relate to those 300 units received by Summit Racing on July 3, 2019. Because Summit Racing is unable to determine whether its customers obtained units which were part of the 300 unit order received on July 3, 2019, or units of the Products that had been in its inventory on July 3, 2019, out of an abundance of caution.
Production Dates :	JUL 03, 2019 - JUL 14, 2020



Number of potentially involved : 419 Estimated percentage with defect : 2 %

**Population :** 

### 20E-093

**20E-093** 

#### Page 2

#### **Description of Defect :**

Description of the Defect :	Although the testing by the independent laboratory confirmed that this Product meets the advertised load capacity when used as described on the Product's warning label, Summit Racing experienced a more than de minimis increase in warranty or quality returns relative to this Product. The testing and analysis of the Product, and the further inspection of the Product, reflect that there appears to be a material risk that the ratchet bar may fail during use of this jack stand which would allow the vehicle to fall without any warning, with the potential to injure persons near or under the lifted vehicle.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	Should the unit experience a failure of the ratchet bar the vehicle will drop suddenly. The type of failure presents an opportunity for vehicle, property, and/or personal harm to occur.
Description of the Cause :	Testing did reveal a failure mode consistent with customer feedback (fractured ratchet bar) when the load was placed on one lug of the ratchet bar saddle. While testing with a centrally located load distribution resulted in no failure, it is possible that the unit may fail when centrally loaded as a result of previous misuse.
· · ·	Visual inspection of the ratchet bar may confirm the presence of a fracture, but it is unlikely that any warning signs will be present before the point of failure.

#### **Involved Components :**

Component Name :	NR
Component Description :	NR
<b>Component Part Number :</b>	NR

#### **Supplier Identification :**

#### **Component Manufacturer**

Name :Haining Lee Ding Machinery Co LtdAddress :F052 baihuihailong 399 Wenyuan Road<br/>Haining Economy Development Zone Haining Foreign StatesCountry :China

The information contained in this report was submitted pursuant to 49 CFR §573

## **Part 573 Safety Recall Report**

**20E-093** 

#### **Chronology** :

Based upon customer feedback concerning this Product that had been manufactured by Haining Lee Ding Machinery Co. Ltd., Summit Racing stopped all sales of the Product as of July 14, 2020, and initiated an investigation which included testing by an independent laboratory, analysis of customer returns of the Product, and an in-depth internal inspection of the Product. Based upon its investigation, Summit Racing decided on December 18, 2020, to conduct a recall to address the quality concerns relative to certain units of the Product.

#### **Description of Remedy :**

Description of Remedy Program	: Summit Racing will refund all customers the purchase price of the item as well as provide an additional \$25.00 Gift Certificate.
How Remedy Component Differ from Recalled Component	
Identify How/When Recall Condition was Corrected in Production	This product has been discontinued as of July of 2020.

#### **Recall Schedule :**

Description of Recall Schedule :	We will begin the recall campaign immediately.
Planned Dealer Notification Date :	NR - NR
Planned Owner Notification Date :	DEC 23, 2020 - FEB 23, 2021

#### **Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR Address : NR NR Country : NR Company Phone : NR

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573